# PERK CHEMICAL CO. ELISABETH, N.J.

BRIAN V. MORAN - ECOLOGY & ENVIRONMENT INC, (TRENTON)

1/8/80 8-342-5500 /(201) 494-5871

MR. MORAN DIS NOT VISIT THE SITE SINCE HIS REPORT (9/11-9/13/1979)
214/80 MESSRS. RON CONCORY AND GEORGE SMAGDA 8 477-7875 PROMISED TO BRING ME UT TO DATE ON PERK! WHERE DOES THE NO STATE ATTORNEY
1) GENERAL GTANDS IN HIS LITIGATION WITH PERK'S CONT'S OPERATION?

2) DID OSHA VISIT SITE ?3) ANY OTHER IT PORTANT IN TO?

2/6/80 FRED RUBEL SUGGESTED TO GALL CHARLES TENERELLA (4-9382), FEDERAL REGIONAL COUNCIL REPRESENTATIVE, MR, TENERELLA WILL LET ME KNOW IF OSHA DID ANYTHING...

2/11/80 CONTROTED MR. RADUL ILAW, US DEPT. OF LABOR-DSHA, 1515 BROADWAY, ROOM 3445, NOWLORK 10036, 212 944-3420 (FTS 8 662-3420) AND ASKED FOR INFO. - IF OSHA VISITED PERK, FOUND VIOLATIONS IF AND PAND OTHER INFO. HE REPLIED THAT DIAM VISITED THIS STALL TYPE OPERATION (WHERE SOME 10 PEOPLE ME IN VOLVED) SOMETIME IN 1977, THERE MAY BE SOME SHALL SAFETY VIOLATIONS. HE ASKED ME TO WRITE HIM AN OFFICIAL LETTER

-WHICH I DID ON 2/12/80. COPY ENCLOSED

2/20/80 MRTICLE IN THE NEWYORK TITTES: PERK AND 2 DTHER COTTAGNIES (WASTE HAULING FIRMS) WERE INDICTED FOR DUTTING A TOTAL OF YOTILLIEN GALLONS OF ACID WASTE INTO MRTHUR VILL FROM 1973 TO 1979 ACCORDING TO THE INDICT-WENT IT SEEMS THAT PERK WAS THE STALLEST OFFENDER, PERK IS ACCUSED OF ONE COUNT OF CONSPIRACY AND THREE COUNTS OF CREATING A NUISANCE AND VIOLATING THE WATER POLLUTION CONTROL ACT THE WAXITUM PENALTY ACAINST IT WAS \$129,000, - (OTHERS: INON OFFICIALS OF PERK CHARGED: RAY ROTSCHILD, PRESIDENT, RALPH BELL WEITH WHITE, TANK-TRUCK DRIVERS.

2/25/80 A FORM. LETTER REPLY ARRIVED FROM OSHA'S AREA DIRECTOR
MR. RIGHARD J. PALMIER: ADVISING THAT I WILL A HEAR OF THE RESULT
OF INVESTIGATION, WHICH COILL BE CONDUCTED, WITHIN A VERY SHORT TIME OF.
I A INFORMED CHARLES TEMERELLA (OFFICE OF FEDERAL HEMINITIES
ROOM 1009, #4-9382) OF THIS LETTER.

ROOM 1009, #4-9382) OF THIS LETTER. OSHA
4/24/80 CALLED MR. I LAW TO BRING THIS VIN VEGTIGATION UP TO DATE, MR.
PALMIERI, AREA DIRECTOR COULD NOT BE REACHED, SO MR. ILAW
WILL CALL BACK WITH REQUESTED INFORMATION MR. I LAW
AMPORTS THAT THE PERK CHETICAL IS BEING TESTED RIGHT NOW. IT
SEEMS A SAFE OPERATION FROM OSHA'S POINT OF VIEW. AS SOON
AS TEST RESULTS ARE OBTAINED EPA WILL BE INFORMED. PERK
GOT A "HOUSEKEEPING CITATION" WHICH SHOULD BE IMPROVED.

6/5/80 OSHA'S REPLY - RECEIVED ON 6/9/1980.

Subject: Investigation Report Concerning the Perk Chemical Company, Elizabeth, New Jersey. Date: 13 September 1979.

Prepared by: Emergency Response and Inspection Branch

#### I. Background

The Perk Chemical Company is a small solvent recovery operation located on 217 First Street in Elizabeth, New Jersey, near the Elizabeth River. The site was brought to our attention through the Enforcement Division who reported that Perk may be storing flammables/combustables adjacent to the large natural gas storage tanks located on Third Avenue. Perk experienced a spill of some 5,000 gallons of perchloroethylene in July 1979 due to a storage tank failure.

Mr. Brian Moran of Ecology and Environment (E & EI) and Mr. John Burger (E & EI) conducted a hazardous waste survey and SPCC inspection concurrently on 7 September 1979. Mr. Ray Rothshild (President of Perk) accompanied us during the investigations.

#### II. Nature of the Materials Disposed of at the Site

The Perk facility reclaims, by distillation, a variety of organic solvents.

The bulk of their business is recovery of perchloroethylene (tetrachloroethylene).

The major flammable organic processed is Methyl Ethyl Ketone (MEK). Table 1

lists the compounds which may be stored on site at any given time.

#### III. Description of Site

The Perk Chemical facility occupies approximately 2 acres on First Street in Elizabeth, New Jersey, about two blocks away from the Elizabeth River. The site is made up of a small office building, a solvent recovery/process area and a large storage area for both receiving raw chemical stocks and storage/ shipping of recovered products. Structures are currently being erected for new

## Oils

Machine oils Cutting oils Cooling oils (no motor oil)

# Emulsions

Oily emulsion - (oil and water or oil and solvent)

# Flammable Organic Liquids (Solvents)

Toluol
Xylol
Mineral Spirits
Naptha
Kerosene
Methanol
Butyl Alcohol
Isopropyl Alcohol
Methyl Ethyl Ketone (MEK)
Acetone
Cyclohexanone

# Acids and Alkali Solutions

Caustic
Detergent with alkaline base
Sulfuric acid
Nitric acid
Acetic acid
Hydrochloric acid

Non-Flammable Organic Liquids (chlorinated solvents)

Tetrachloroethylene Trichloroethylene 1,1,1 Trichloroethane Methylene Chloride production facilities. Approximately 600 feet away from the northwest corner of Perk's property are two large natural gas storage structures. Mr. Rothshild stated that he did not wish any photographs of the facility taken for our records. Therefore, no photos were taken of the site.

#### IV. Description of Surrounding Area

The Perk facility is located in a predominantly industrial area. Residential areas are located two blocks north and east of the Perk facility. The area is located in a 100 year floodplain area. The potential for contamination of public drinking water is minimal, since the closest public water supply (Elizabethtown Water Supply) is at least six miles away.

#### V. Geology and Groundwater

The Perk site is at an elevation of 10 feet throughout. The property is covered by both gravel and pavement. There was no evidence of runoff or erosion at the site.

#### VI. Sampling and Chemical Analysis of Samples

No samples are known to have been taken during the July spill incident or otherwise.

## VII. Status of Local, State Involvement

Perk Chemical Company has applied for a DPCC<sup>1</sup> permit. So far, the permit has been denied. Apparently, Perk cannot implement their spill control program until an easement of the property with the U.S. Corps. of Engineers is settled. Also, according to Mr. DuHammel (N.J.D.E.P.) there has been no permit granted to operate the facility for the following reasons:

- 1. Spill cleanup facilities are inadequate.
- 2. Facility has too many drums stored.
- 3. Drum stacking procedures do not comply with New Jersey State

Discharge Prevention Control and Countermeasure Plan

#### regulations.

The case is currently under litigation with the Attorney General's Office concerning the continued operation of the plant.

Conversations with Captain Gannon (City of Elizabeth Fire Prevention Bureau) lead us to believe that there is no apparent fire/explosion hazard to the natural gas storage tanks located on Third Avenue. The closest part of Perk's property lies some 600 feet away from the tanks. Oil drums (full) are known to be stored on this portion of the property. This section and other drum storage areas on the Perk site were sampled for explosive gases during the investigation. No evidence of explosive gases using the explosive meter were found in the storage areas.


According to Captain Gannon, the City of Elizabeth inspects the facility for fire/explosion hazards 2-3 times a year. There are currently no violations cited against Perk by the City.


# VIII. Discussion of Imminent Hazard Aspects of Site

The Perk facility is an active chemical refining facility, not a hazardous waste dump site. Although no immediate environmental hazards were evident at the Perk site during the investigation, there may be occupational hazards present for the process and plant operators. While surveying the plant, strong halogenated organic solvent odors were evident around the immediate chemical process area. It is suggested that OSHA be contacted for an inspection of the facility for compliance with PL 91-596, the Occupational Safety and Health Act.

#### Attachments:

- 1. Map
- Site Plan
- 3. Survey Forms





# Ruptured tank spews toxin in Elizabeth

By ZANA W. COCO

Several thousnd gallons of the dry cleaning solvent perchlorethylene leaked onto an Elizabeth street and down two catch basins yesterday when a storage tank ruptured at a chemical waste firm.

No one was injured in the accident.

Workmen from Park Chemical Co., which owns the tank, began to mop up the spill which occurred shortly after 10:30 a.m. at 217 S. First St.

Officials said the black murky cleaning solvent had leaked from the ruptured tank housed at the front of the firm's property, forcing Elizabeth police to close the street to traffic.

A 6,000 gallon vacuum truck, owned by the company, was used to remove all the spilled chemical and sandbags were placed in the sewer lines to stop the flow, according to John Surmay, city health, welfare and housing director.

The firm also washed down the street to remove any

excess spillage, he said.

City health officials were initially concerned over whether the chemical which entered the catch basins would have a serious affect on the treatment of sewerage after it reached the Joint Meeting Sewerage Authority plant a mile away.

However, Mike Brinker, executive director of the treatment plant said although workers noticed small traces of the chemical in the effluent, he did not think it was enough to cause alarm. As a precaution, however, he ordered his workers to take water samples every 15 minutes instead of hourly.

Ray Rothschild, owner of the chemical firm, said he did not know what caused the tank to rupture at the seams and would investigate the accident. He estimated less than 5,000 gallons of the solvent were in the tank at the time of the accident.

The firm receives chemical waste in drums and either sells it for recovery or re-use, or blends the wastes

to produce other saleable mixtures.

The firm had applied to the Department of Environmental Protection's Solid Waste Administration in February for a permit to operate a special waste treatment and recovery and transfer facility.

In March, the city asked that nine conditions be imposed on the firm before issuing the permits, Surmay

said

The recommendations called for the firm to store all hazardous and flammable material in clearly-marked drums, and in separate areas to conform with the National Fire Prevention Association standards.

The city also recommended drums be stored away from the fencing and that an eight-inch curb be con-

structed to contain leakage.

									REGION	t l'arra	
	U. S. ENVIRONMENTAL PROTECTION AGENCY HAZARDOUS WASTE SITE INVESTIGATION LOG					•	Final Strategy Determinations				
Site Name PERK CHEMICAL Co.  Site Name 1:  Site Address 217 S. 157 St.  ELISABETH, N.S.  brief description of the type of facility and hazard information (indicate active or inactive)	Problem Identification (Date) Source of Identification	<del> </del>	Preliminary Assessment (Date, Regional contact)	Apparent Serious- ness of Problem (High-Medium- Low-None)	Site Inspection Agency Performing Inspection (Dates)	Tentative Disposition (Date, Regional contact)	Corrective Action Underway (State, Federal Private Enforcement	(State, Federal) (if State, date to be initiated) (if Federal, Date Case Development Plan Prepared)	Corrective Action Plan Developed but No Resources Available for Implementation (Date), Regional Contact)	No Action Necessary (Date of determination) STATION (COMPLETED	
THIS IS AN ACTIVE CHETTICAL REFINING FACILITY, NOT A HAZARDOUS WAGTE DUMP SITE DREAMIC SOLVENTS REQUERY PLANT	ENFORCEMENT Division 6   14179	Smir or N.J.⊕ 7/25/79	ONGOING 9/11/79 BRIANV.HORA	VOLATILIE SOLVENTS (S)	ERVIB 91 179 BRIAN HARA						
NO IMMEDIATE ENVIRONDIENTAL HAZARSS ARE EVIDENT, BUT OCCUPATIONAL HAZARSS TO PERSONNEL MAY BE PRESENT (STRONG ODORS OF HALOGENATED ORGANIC SOLVENTS WERE EVIDENT). IT WAS SUGGESTED TO CONT. ACT OSHA	•		(EVE, INC)	SONE FLAMMABLE SOLVENTS (B) (METHYL - GTALL KETONE	EDE LAC)						
SPILLED 5000 GALLONS OF PERCHLOROETHYLENE IN JULY 1979, TO 195UE A PERRIT.  STATE OF N.J. REFUSES PERMITSION TO OPERATE THE FACILITY (UNDER LITIGATION WITH ATTORNEY GENERAL'S OFFICE)	; <del>-</del>										
Co. HOLDS A STATE PERMIT, TYPE: DPCC											
				The state of the s							